Martha G. VanGeem¹, Kami Farahmandpour¹, and John Gajda¹

CASE HISTORIES OF BUILDING MATERIAL PROBLEMS CAUSED BY CONDENSATION AT AN ENCLOSED SWIMMING POOL AND AN ENCLOSED ICE RINK

Reference: VanGeem, M.G., Farahmandpour, K., and Gajda, J., **"Case Histories of Building Material Problems Caused by Condensation at an Enclosed Swimming Pool and an Enclosed Ice Rink,"** *Water Problems in Building Exterior Walls: Evaluation, Prevention, and Repair, ASTM STP 1352*, J.A. Boyd and M.J. Scheffler, EDS., American Society for Testing and Materials, West Conshohocken, PA, 1999.

Abstract: Enclosed swimming pools and ice rinks in winter climates have the potential for high indoor relative humidities and cold building materials. These elements can contribute to condensation and premature deterioration of building materials. Case histories are provided for an enclosed swimming pool and an enclosed ice rink with condensation problems.

An evaluation was performed after roof leaks were reported at a recently constructed indoor swimming pool in a Chicago suburb. After a preliminary inspection, it was evident that the reported leaks were related to building moisture problems rather than a roof leak. Exterior brick masonry exhibited heavy efflorescence in the area of the swimming pool, and water streaks were visible on the exterior walls below the eaves. The evaluation included laboratory testing, a visual inspection, field tests and measurements, and analyses for condensation potential. Results of the evaluation indicated the presence of condensed moisture as a direct cause of the observed water stains, and masonry efflorescence. Recommended corrective actions developed.

A 54-year-old enclosed ice rink in New England was under investigation to determine the cause of a deteriorated wood deck roof. The building did not have dehumidification or air handling systems, and was heated only when occupied. The evaluation included visual inspection and analyses for condensation potential. Results of the evaluation indicated condensation within the wood decking and insulation during winter months, and high relative humidities that prohibited drying during the spring, summer, and fall. These conditions, over an extended number of years, resulted in decay of the wood decking.

Keywords: Condensation, Efflorescence, Ice rink, Moisture migration, Swimming pool

¹Principal Engineer, Principal Engineer, and Senior Engineer, respectively, Construction Technology Laboratories, Inc., 5420 Old Orchard Road, Skokie, IL 60077. All authors are Licensed Professional Engineers.

Introduction

Enclosed swimming pools and ice rinks in winter climates have the potential for high indoor relative humidities and cold building materials. These elements can contribute to condensation and premature deterioration of building materials. Buildings with lower relative humidities in these climates tend to be more forgiving because they have opportunities to dry out. Moisture due to rain or floods penetrating the building envelope tends to evaporate from low relative humidity buildings in the winter. Moisture due to indoor moisture migrating outwards during the winter tends to evaporate in the summer months. Buildings with high interior relative humidities throughout the year do not have these forgiving seasons, and must be carefully designed to prevent moisture problems. Case histories are provided for an enclosed swimming pool and an enclosed ice rink with condensation problems.

Enclosed Swimming Pool

An evaluation was performed after roof leaks were reported around some skylights of a newly constructed indoor swimming pool. Comparing reports of roof leaks to weather data indicated no correlation with precipitation, but a good correlation with low temperatures. A preliminary inspection revealed no indication of roofing deficiencies or water leakage around windows or skylights. Exterior brick masonry exhibited excessive efflorescence in the area of the swimming pool (Figure 1), and water streaks were visible on the exterior walls below the eaves (Figure 2).



Figure 1 – Area of Severe Efflorescence on the Exterior of the Pool Area



Figure 2 – Water Staining below Eaves on the Exterior of the Pool Area

The evaluation included a visual inspection, Fourier transform infrared spectrometry (FTIR) analysis on water stains on the masonry walls, borescope inspection through roof and wall assemblies, measurements of interior relative humidities and temperatures, measurement of interior-exterior pressure differentials, and exploratory openings made through the roof assembly. Analyses were performed to evaluate condensation potential through the roof and wall assemblies under actual and design conditions. Condensation rates were calculated for each case. Results of the evaluation indicated presence of condensed moisture as direct cause of the observed water stains, reported leaks and masonry efflorescence.

Building and Materials

The indoor swimming pool facility is located in a Chicago suburb and was completed in fall 1994. The building includes an indoor swimming pool area, workout room, offices, and a second floor lounge. The swimming pool area also includes a large whirlpool.

The swimming pool area structure has a steep roof and consists of masonry loadbearing walls supporting laminated wood trusses and laminated tongue and groove wood decking. The tongue and groove wood decking is exposed to the inside of the swimming pool area. Design drawings indicate a rigid insulation layer placed over the tongue and groove wood decking. Prefabricated ventilated deck boards consisting of two-oriented strand boards (OSB) with a 16-mm (⁵/₈-in.) air gap were attached over the rigid insulation. The ventilated deck boards and rigid insulation were provided as a pre-assembled system. Roofing felt and asphalt shingles were installed over the ventilated deck boards. Several rectangular skylights were installed over the roof. In some areas, such as roof ridges and areas adjacent to skylights, a layer of ice and water shield protection membrane was substituted for the roofing felt.

The walls in the pool area consist of cement plaster interior surfaces installed over concrete masonry units (CMU), 50-mm (2-in.) rigid insulation on the outer face of the CMU, and face brick.

Exterior windows are wood framed and have insulated glass panes. Skylights are aluminum framed and reported to have argon-filled insulated glass panes.

The building HVAC system was reportedly designed to provide negative interior pressure during the winter months and to maintain an indoor relative humidity of approximately 40%. However, the owner indicated that the HVAC system for the pool area was not operated continuously.

Concern was due to apparent water leaks at the skylights during cold winter days, brown colored water stains that had appeared on the masonry surfaces at the eaves of the roof in the pool area, and efflorescence of exterior masonry surfaces around the pool area. These symptoms became evident during a cold January immediately following completion of the building and filling of the pool with water.

Scope of Evaluation

The scope of evaluation included a limited field investigation, laboratory testing, and analysis for condensation potential. Available design drawings and specifications were reviewed to evaluate possible design deficiencies. Fourier transform infrared spectrometry (FTIR) analysis was performed on brown colored water samples removed at the roof eaves and water-soluble compounds of the roof deck components.

A visual review of the building interior and exterior surfaces was performed. The interior area adjacent to a skylight was inspected from a scaffold. A 38-mm (1½-in.) hole was drilled through the tongue and groove wood deck, insulation, and bottom layer of OSB to evaluate the absence of a vapor retarder and the condition of the ventilated deck board above. Relative humidities and temperatures were measured at several locations inside the building, and at one location outside the building.

Pressure differential between the outside and inside of the building was measured twice during our fieldwork. Borescope inspections were performed at two locations of the exterior pool area walls to evaluate the wall construction and to verify absence of a vapor retarder.

In order to evaluate the affect of the predicted condensation on the roofing system components, shingles were removed from the exterior roof surfaces to expose the OSB boards. Shingles were removed in several areas including an area adjacent to a skylight, and an area in the field of the roof.

A steady-state water vapor diffusion analysis was performed for the typical roof and wall sections to verify the potential for condensation in the existing structure. The analysis was also performed for the proposed repairs to investigate their potentials for condensation. The analyses provided the location of the surfaces on which condensation potentially occurs as well as the quantity of condensed water. Analyses were performed in accordance with ASTM C 755-85, Standard Practice for Selection of Vapor Retarders

for Thermal Insulation. Analyses were performed for the following outdoor temperature and relative humidity conditions:

- ASHRAE summer and winter design conditions [1]
- NOAA average January, February, and July conditions [2]
- Conditions observed on March 1, 1995 during the field investigation

The indoors were assumed to be at standard indoor pool conditions of 27°C (80°F) and 95% relative humidity. Although the relative humidity in the pool area was generally maintained at a lower relative humidity, the HVAC system was not operated continuously. Therefore, the 95% relative humidity represents a worst case scenario.

Results of Field Investigation and Laboratory Testing

Laboratory testing of the brown stained water samples taken at pool area roof eaves indicated that the source of brown colored material was the OSB of the ventilated deck boards.

Review of the design drawings indicated no effective vapor retarder was provided on the inner or warm surfaces of the roof and walls in the pool area. The ice and water shield protection installed over the ventilated deck boards did not act as an effective vapor retarder. Designers had attempted to prevent condensation by use of the ventilated deck boards. The air gap between the deck boards was intended to be ventilated through continuous eaves and ridge vents. However, this ventilation was ineffective due to wood blocking specified at the eaves immediately above the eaves vents. In addition, the lower OSB of the ventilated deck became cold enough in winter conditions to cause condensation. Therefore, ventilating the upper deck panels would not eliminate condensation. Design drawings did not indicate asphalt felt above the tongue and groove wood deck. The design of exterior walls did not provide an effective vapor retarder within the wall system.

Visual review of the building exterior confirmed presence of several brown stains on the brick masonry immediately below the pool area roof eaves (Figure 2). These stains were not limited to the areas below the skylights and appeared uniformly distributed. It appears that the staining was caused by condensed water that formed on the outside surfaces of the ventilated deck boards. This condensed water would dissolve brown, water-soluble compounds within the OSB and would flow down the roof deck, discharging at the eaves.

Observations within exploratory openings into the exterior roof surface revealed water damage to the OSB boards in all cases (Figure 3). The water damage was accompanied with mildew in areas adjacent to the skylight. This condition was attributed to presence of the ice and water protection membrane placed over the outer OSB board in those areas. The presence of this relatively impermeable layer slowed evaporation of the condensate from the OSB boards and promoted mildew growth. In all exposed areas, the damage caused by the condensation was severe enough to adversely affect the physical characteristics of the OSB boards.

Severe efflorescence was observed on exterior masonry surfaces at the north wall (Figure 1). Efflorescence was also observed on the east and west walls of the pool area as well as the fireplace chimney on the east elevation. The fireplace was located in a lounge area adjacent to the pool area.



Figure 3 – Water Damage to OSB

Measured relative humidities and temperatures during the afternoon of March 1, 1995 were as follows:

- Indoor relative humidities in the pool area ranged from 34% to 38%.
- Indoor temperatures in the pool area ranged from 26°C (78°F) to 27°C (81°F).
- Outdoor relative humidity was 41%.
- Outdoor temperature was -5°C (23°F).

The exploratory hole drilled adjacent to a skylight revealed the following:

- No vapor retarder or asphalt felt was found directly above the tongue and groove wood deck.
- The OSB of the ventilated deck board was notably moist.

Two measurements of pressure differential between the outside and inside of the building were taken with a digital micromanometer at an approximate height of 1-m (3 ft) above the pool deck. Measurements indicated that the interior pool air pressure was 5 Pa (0.02 in. of water or 0.0007 psi) lower than that of the outside. This minor pressure differential was induced by the HVAC system.

Borescope inspection of the exterior pool area walls at one north facing location and one west facing location indicated the absence of a vapor retarder immediately underneath the interior plaster finish. Based on these two observations, the walls were assumed to consist of cement plaster on metal lath, kraft paper, a 45-mm (1³/₄-in.) air space, CMU, kraft paper, 50-mm (2-in.) of rigid insulation (assumed to be polyisocyanurate), and face brick.

Results of Analyses

A steady-state vapor diffusion analysis was performed assuming the wall dimensions and materials cited above, and the following roof dimensions and materials: a 50-mm (2-in.) thick tongue and groove wood deck, a 7-kg (15-lb) asphalt felt, 65-mm (2 9/16-in.) thick polyisocyanurate insulation, two layers of 11-mm (7/16-in.) OSB separated by a 21-mm (13/16-in.) non-ventilated air space, 7-kg (15-lb) asphalt felt, and asphalt shingles. The air gap between the two OSBs was assumed to be non-ventilated because wood blocking installed at the eaves would prevent airflow through the gap. In addition to existing conditions, analyses were performed for assumed repairs of adding a vapor retarder to the roof and wall assemblies. Results (Tables 1 and 2) indicate the following:

- The existing roof was predicted to have condensation between the insulation top surface and OSB for all winter conditions analyzed. Condensation was also predicted to occur beneath the insulation for the winter design case, the average January case, and the average February case. The condensation rates were considered low (underestimated) due to gaps in the wood deck and insulation boards.
- The existing wall was predicted to have condensation between the insulation and brick for all winter conditions analyzed.
- The assumed roof repair was the addition of a continuous warm side 0.15-mm • (6-mil) polyethylene vapor retarder with a ventilated air space beneath the vapor retarder. This repair indicated condensation potential at the interface between top of the insulation and the bottom of the OSB for the severe ASHRAE winter design, the average January, and the average February cases when 95% RH was assumed for the indoor air. No condensation potential was indicated when the ASHRAE winter design, the average January, and the average February cases were assumed to have indoor relative humidities of 22, 46, and 53%, respectively. The ASHRAE winter design condition is a severe case for condensation and is anticipated to be exceeded 2.5% of the hours in the months of December, January, and February, which is 54 winter hours. Condensation predicted to occur only under these conditions is frequently able to evaporate during other periods and not cause damage. The predicted relative humidity to prevent condensation potential for the average January and February cases were greater than the reported design relative humidity of 40%. This repair was considered adequate for the conditions assumed.
- The assumed wall repair was a continuous 0.15-mm (6-mil) polyethylene vapor retarder placed on the existing wall surface and a water resistant wall board placed on the inside surface of the vapor retarder. It was also assumed that a vapor retarding paint was applied to the interior surfaces of the wallboards. Analyses of this repair indicated a condensation potential at the interface of the insulation and brick for the severe ASHRAE winter design and average January cases when 95% relative humidity was assumed for the indoor air. No condensation potential was indicated when the ASHRAE winter design and average January cases were assumed to have indoor relative humidities of 39 and 88%, respectively. The predicted relative humidity to prevent condensation potential for the average January case is greater than the reported room relative humidity of 40%. This repair was considered adequate for the conditions assumed.

	sation Rate	grains/day/ft ²	2.2	12.8	11.2	10.8					1.1		0.7		0.7			I	
densation	Conder	g/day/m²	1.5	8.9	7.8	7.5	I				0.8	I	0.5	I	0.5	I	I		
Con	Interface	of Condensation	Insulation / OSB	Insulation / OSB	Insulation / OSB	Insulation / OSB	None	None		None	Insulation / OSB	None	Insulation / OSB	None	Insulation / OSB	None	None	None	
ondition	Relative	Humidity, precent	41	70	70	70	70	70		41	70	70	70	70	70	70	70	70	
tdoor Co	erature	Ц. °	23	2	21	26	91	73	ç	N N	2	2	21	21	26	26	91	73	
no	Tempe	°	-5	-17	9	ကု	33	23	L	ဂု	-17	-17	9-	9	ကု	ကု	33	23	
ndition	Relative	Humidity, precent	38	95	95	95	95	95	C	38	95	22	95	46	95	53	95	95	
door Co	erature	Ц.	78	80	80	80	80	80	0 1	8/	80	80	80	80	80	80	80	80	
<u> </u>	Tempe	ů	26	27	27	27	27	27	ç	97	27	27	27	27	27	27	27	27	
		Case	Observed 3/1/1995	Winter Design	Avg. January	Avg. February	Summer Design	Avg. July		Observed 3/1/1995	Winter Design	Winter Design	Avg. January	Avg. January	Avg. February	Avg. February	Summer Design	Avg. July	
		Component	Existing Roof							Assumed	Repaired Roof								

TABLE 1 - Results of the ASTM C755 Steady-State Vapor Diffusion Analyses to Determine the Condensation Potential of the Roof

	sation Rate	grains/day/ft ²	2.2	14.6	13.0	12.1		I	I	0.7		0.1	I		I	Ι
ndensation	Conder	g/day/m ²	1.5	10.1	9.1	8.5	I		I	0.5	I	0.0	I	I	I	I
Cor	Interface	of Condensation	Insulation / Brick	Insulation / Brick	Insulation / Brick	Insulation / Brick	None	None	None	Insulation / Brick	None	Insulation / Brick	None	None	None	None
ondition	Relative	Humidity, precent	41	70	70	70	70	70	41	70	70	70	70	70	70	70
tdoor Co	erature	ĥ	23	N	21	26	91	73	23	N	N	21	21	26	91	73
no	Tempe	°	-5	-17	ę	ကု	33	23	-5	-17	-17	9	φ	ကု	33	23
ndition	Relative	Humidity, precent	38	95	95	95	95	95	38	95	39	95	88	95	95	95
door Coi	erature	Ц. °	78	80	80	80	80	80	78	80	80	80	80	80	80	80
<u> </u>	Tempe	ů	26	27	27	27	27	27	26	27	27	27	27	27	27	27
		Case	Observed 3/1/1995	Winter Design	Avg. January	Avg. February	Summer Design	Avg. July	Observed 3/1/1995	Winter Design	Winter Design	Avg. January	Avg. January	Avg. February	Summer Design	Avg. July
		Component	Existing Wall						Assumed	Repaired Wall						

TABLE 2 - Results of the ASTM C755 Steady-State Vapor Diffusion Analyses to Determine the Condensation Potential of the Wall

 No condensation was predicted for the summer conditions assumed for the wall or roof as they existed or as they were proposed to be repaired.

As mentioned previously, ASHRAE winter and summer design conditions are often severe cases for condensation. Condensation predicted to occur only under these conditions is frequently able to evaporate during other periods and not cause damage. However, continuous condensation with no drying periods will result in the accumulation of moisture in the building envelope.

Calculation assumptions may not replicate field conditions. The analysis method is a steady-state first order method used to show the potential for condensation. The method does not consider the dynamic effects of daily temperature changes, solar effects, and material absorption. Therefore, condensation rates are approximate and are better suited as rough approximation rates for comparison purposes rather than actual volumes of water.

Findings

In general, the reported leaks at the skylights in the pool area were attributed to condensation in the roof assembly. The brown stains at the exterior walls were also attributed to this condensation. As water condensed in the roof assembly, it leaked to the interior at the skylight openings, or ran down over the surfaces of the OSB and discharged at the eaves.

The condensation in the roof assembly was caused by lack of an effective vapor retarder on the interior surfaces of the roof assembly. Condensation caused damage to the ventilated deck boards and other roof assembly components.

The efflorescence observed on the exterior masonry was also attributed to lack of an effective vapor retarder. In absence of an effective vapor retarder, warm, humid air from the pool area penetrated the porous plaster finishes, CMU, and rigid insulation. As it reached the colder surfaces of the exterior brick it condensed. This condensed moisture was continuously driven towards the outside by higher water vapor pressure on the inside. As it passed through the porous mortar, it dissolved water-soluble salts such as calcium carbonate and brought these salts to the outside surfaces of the brick. Eventual evaporation of the moisture left these salts on the masonry surface in form of the observed efflorescence.

In most indoor swimming pool buildings, controlling the indoor relative humidity and reducing interior atmospheric pressure minimizes the moisture drive from interior building surfaces to the outside. Reduction of interior atmospheric pressure is accomplished by a negative pressure HVAC system. Although indoor relative humidity of the facility was well controlled at times, its atmospheric pressure was not maintained at a significantly lower pressure than that of the outdoors. This resulted in excessive moisture penetrating the building envelope.

Recommendations

The only effective method to prevent condensation in such a building is to provide a continuous and adequate vapor retarder on all interior surfaces of the pool area and maintain a constant negative indoor pressure.

Recommendations for installing a vapor retarder in the roof assembly were to remove all components down to the tongue and groove wood deck, and to rebuild them. The new roof assembly was designed to contain a ventilated air gap between the top of existing tongue and groove decking and a new vapor retarder. Adequate insulation, nailer boards, and roofing materials were specified over the vapor retarder.

Recommendations were to provide a continuous vapor retarder in the exterior wall assemblies by installing a vapor retarder over the existing interior surfaces. A layer of moisture-resistant wallboard (such as cement board or cement plaster) was recommended over the vapor retarder. It was also recommended that the interior surfaces of the wallboard be finished and painted with a vapor retarding paint.

For long- term prevention of moisture problems, recommendations were to install the vapor retarder in the walls between the pool area and the workout room, offices, and second floor lounge.

Enclosed Ice Rink

An analysis was performed to determine the potential for condensation within the roof materials of an enclosed ice skating rink as it was originally constructed in 1938. The building was located in New England. An elastomeric spray-applied membrane was applied to the exterior roof surface in 1987. The purpose of the analysis was to determine whether enough condensate was present to be absorbed by the insulation and wood deck to cause significant deterioration of the wood deck prior to the application of the roof membrane.

Building and Materials

The steel frame building housing the indoor ice skating rink was constructed in 1938. The building includes a main rink area and adjacent mechanical and office areas. The building exterior walls consist of 200-mm (8-in.) concrete masonry blocks with single-pane steel frame windows. A previous investigation of the building indicated walls and windows were not airtight; and windows were single glazed with old, deteriorated and broken glass. There were visible gaps at the wall-to-roof connection at the rake detail. The walls were single wythe concrete masonry and were step cracked in some areas. This information indicated the building had a relatively high infiltration rate. Building infiltration rates generally range from 0.2 to 2 air changes per hour (ACH) [1]. Since the information provided indicated a relatively leaky building, an infiltration rate of 1 ACH was assumed for analyses.

No dehumidification or air handling system was incorporated into the design of the building. Fog routinely formed above the ice rink in the summer, and condensation was pervasive on the steel structural members of the roof. Pools of water formed on the ice in the summer months due to condensate dripping from the ceiling. This condition reduced skating quality and contributed to unsafe conditions. The ice provided a continual source of water vapor to the building air.

Evidence of fog in the building in the summertime, the condensate in the summertime and the lack of dehumidification equipment indicated the building relative humidity was greater than 80% and probably close to 100%. Building relative humidities were assumed to be 80% in the winter and 99% in the summer for analyses.

The building was heated to $13^{\circ}C$ (55°F) only during occupied periods. Therefore, the temperature of the rink in the winter was assumed to be $13^{\circ}C$ (55°F) or lower. The temperature of the rink in the summer was not reported in available information and was assumed to be $21^{\circ}C$ (70°F) or lower.

The rink area has an arched roof that consists of steel girders spanning the entire width of the rink, and steel purlins. The original roof deck consisted of 50-mm (2-in.) tongue and groove wood decking supporting a built-up roof membrane.

A 50-mm (2-in.) layer of insulation was installed underneath the wood decking. According to an insulation manufacturer's representative interviewed over the telephone, the insulation produced at that time was most probably sugar cane as currently specified by ASTM C 208, Standard Specification for Cellulosic Fiber Insulating Board. This specification covers boards made from wood or cane. The thermal conductivity of this material was assumed to be 0.048 W/m·K (0.33 Btu·in./hr·ft².°F) [3]. The permeance was assumed to be 300 ng/Pa·s·m² (5 perms) based on a conversation with an insulation manufacturer's representative and ASTM C 208. Reportedly, the insulation boards were installed under pre-assembled deck panels before installation over the steel purlins. This resulted in a layer of insulation between the wood decking and steel purlins.

The 50-mm (2-in.) wood decking was assumed to have the thermal conductivity of pine, which is 0.15 W/m·K (1.06 Btu·in./hr·ft^{2.°}F) [1]. The permeability was assumed to be 4.2 ng/Pa·s·m (2.9 perm·in.) [1].

When analyzing moist wood decking and insulation, permeances and thermal conductivities were estimated to be twice that of dry materials.

Built-up roofing was assumed to have a thermal conductance of $17 \text{ W/m}^2 \text{ K}$ (3 Btu/hr·ft²·°F) [1], and a permeance of 0 ng/Pa·s·m² (0 perms) [1].

Scope of Evaluation

A steady-state water vapor diffusion analysis was performed for the roof of the enclosed ice rink to determine the surfaces of condensation and an estimated quantity of condensate at those surfaces. The analysis was performed for design summer and winter climatic conditions and average summer and winter climatic conditions.

Results of Analyses

A steady-state water vapor diffusion analysis was performed in accordance with ASTM C 755. Average and design winter and summer temperature conditions were assumed for the analysis.

Winter - Results (Tables 3 and 4) showed that significant amounts of water moved from the indoors through the insulation and wood deck and condensed in these materials during average winter weather conditions and winter design conditions. Since 1 gram of water is approximately equal to one milliliter, approximately 97 ml of water accumulate within or on each square meter (10.76 square feet) of the insulation and wood decking during each week in January. Condensation rates were nearly twice as high when the material properties reflect the moisture in the materials. Condensation rates were also doubled for the winter design condition as compared to the average January condition.

TABLE 3 - Results of the Steady-State Vapor Diffusion Analyses to Determine the Condensation Potential of the Roof with Wet Materials

	ц	door Cor	ndition	Ou	tdoor Cc	ndition	Cor	Idensation	
	Temp	erature	Relative	Tempe	erature	Relative	Interface	Conder	sation Rate
Case	ů	Ц. °	Humidity, precent	ů	Ц. °	Humidity, precent	with Condensation	g/day/m²	grains/day/ft²
Winter Design	13	55	80	-13	6	60	Insulation / Deck Deck / Roofing	19.5 5.2	28.0 7.5
Avg. November	13	55	80	7	45	60	Insulation / Deck Deck / Roofing	1.4 0.8	2.0 1.1
Avg. December	13	55	80	-	34	60	Insulation / Deck Deck / Roofing	8.6 2.6	12.3 3.7
Avg. January	13	55	80	7	30	60	Insulation / Deck Deck / Roofing	10.8 3.2	15.4 4.6
Avg. February	13	55	80	.	31	60	Insulation / Deck Deck / Roofing	10.1 3.1	14.6 4.4
Avg. March	13	55	80	ю	38	60	Insulation / Deck Deck / Roofing	6.2 2.0	8.8 2.9
Avg. April	13	55	80	6	49	60	None		Ι
Summer Design	21	70	66	29	85	60	None		I
Avg. July	18	65	66	23	74	65	None	I	I

u	door Cor	ndition	nO	tdoor Co	ndition	Cor	ndensation	
Tempe	erature	Relative	Tempe	erature	Relative	Interface	Condei	ısation Rate
ů	Ц. °	Humidity, precent	ů	Ц. °	Humidity, precent	with Condensation	g/day/m ²	grains/day/ft²
13	55	80	-13	6	60	Insulation / Deck Deck / Roofing	37.1 10.1	53.1 14.6
13	55	80	7	45	60	Insulation / Deck Deck / Roofing	2.3 1.4	3.3 2.0
13	55	80		34	60	Insulation / Deck Deck / Roofing	16.0 5.1	22.9 7.3
13	55	80	÷	30	60	Insulation / Deck Deck / Roofing	20.1 6.2	28.9 8.8
13	55	80	.	31	60	Insulation / Deck Deck / Roofing	19.1 5.8	27.3 8.4
13	55	80	ю	38	60	Insulation / Deck Deck / Roofing	11.4 3.8	16.3 5.5
13	55	80	6	49	60	None		I
21	70	66	29	85	60	None		I
18	65	66	23	74	65	None	I	I

TABLE 4 - Results of the Steady-State Vapor Diffusion Analyses to Determine the Condensation Potential of the Roof with Dry Materials

The calculated condensation in the insulation and wood decking for the months of November through March was 3 liters per m² (0.27 quarts per sq. ft) of ceiling per year when the materials were analyzed as wet. For a 2970 m² (32,000 sq. ft) ceiling, the condensation rate was 8,300 liters (2200 gallons) per year. For the 54 years from 1938 to 1992, when a new roof was installed, this condensation rate was predicted to be 170 liters per m² (15 quarts per sq. ft) or 443,000 liters (117,000 gallons) for the total ceiling.

The moisture from the high relative humidity of the ice rink was trapped in the building by the low permeability of the built-up roofing. The heating system did not remove moisture from the building, and no dehumidification system was installed.

Spring and Fall – Conditions were assumed to be similar in the spring and fall. Although no condensation was predicted to occur during average April conditions (Tables 3 and 4), these conditions did not allow the insulation and wood deck to dry. The built-up roof prevented the materials from drying to the outdoors. Calculations indicated the vapor pressures for saturated insulation and wood decking were approximately equal to the vapor pressures in the building air, and therefore, the materials would not dry to the interior.

Summer - The results for average July and summer design (Tables 3 and 4) show that no condensation occurred during these conditions. The indoor relative humidity was at or near 100% as evidenced by fog near the rink. The built-up roofing prevented the wood decking and insulation from drying to the outside. The potential for drying to the indoor air was limited due to its high relative humidity.

Sublimation of the ice to water vapor will continually increase the relative humidity of the building air until it reaches 100%, and then it will form condensate on the ice and any surface cooler than the indoor air. Infiltration of warm humid air from outdoors will increase the relative humidity of the building air whenever the outdoor air has higher total humidity (moisture content) than the indoor air. If the building air is at 100% relative humidity then the same conditions will cause condensate on any surfaces cooler than the indoor air. If the building air is assumed to be 21°C (70°F) and 100% relative humidity in the summer, infiltration of outdoor air will cause condensate on any surface cooler than 21°C (70°F) at outdoor air temperatures of 29, 27, 24, and 21°C (85, 80, 75, and 70°F) if the relative humidities are greater than 61, 72, 85, and 100%, respectively. Lower building air temperatures will cause greater condensation and it will start to occur at lower outdoor air relative humidities.

Once again, calculation assumptions may not replicate field conditions. The analysis method was a steady-state first order method used to show the potential for condensation. The method does not consider the dynamic effects of daily temperature changes, solar effects, and material absorption. It is further assumed that insulation and wood decking joints and roof punctures do not provide a path for moisture to penetrate. Therefore, the condensation rates are approximate and are better suited as average, approximate rates for comparison purposes rather than actual volumes of water.

Findings

Average winter conditions indicated moisture would migrate from the building air to the insulation and wood decking and condense within them. Average spring and fall conditions indicated the water vapor pressures in the building air and the moist materials were similar, thereby preventing the drying of the insulation and wood decking. Average summer conditions indicated high indoor air relative humidities that limited drying of the insulation and wood decking. These conditions over an extended number of years resulted in the accumulation of moisture in the insulation and wood decking. The high moisture content in the wood decking led to fungi attack and wood decay. Development of repair options was not in the scope of work.

Summary and Conclusions

Evaluations were performed for an enclosed swimming pool and an enclosed ice rink with moisture problems. The analysis method was a steady-state first-order method used to show the potential for condensation. High relative humidities within buildings and the lack of effective vapor retarders led to undesirable condensation in both cases.

For the enclosed swimming pool, the reported leaks at the skylights in the pool area were attributed to condensation in the roof assembly. The brown stains at the exterior walls were also attributed to this condensation. As water condensed on the ventilated deck boards, it either leaked to the interior at the skylight openings, or ran down over the surfaces of the OSB and discharged at the eaves. The condensation in the roof assembly was caused by lack of an effective vapor retarder on the interior surfaces of the roof assembly. The efflorescence observed on the exterior masonry was also attributed to lack of an adequate vapor retarder.

In the enclosed ice rink, moisture migrated from the building air to the insulation and wood decking and condensed within them during winter months. Relative humidity and temperature conditions of the indoor and outdoor air during other months prevented these materials from drying. These conditions over an extended number of years resulted in the accumulation of moisture in the insulation and wood decking, and subsequent deterioration of the wood decking.

Both buildings were classic examples of how inadequately designed or constructed buildings can suffer severe moisture related problems.

The enclosed swimming pool was constructed without an adequate vapor retarder. Additionally, the general lack of a negative indoor pressure and non-continuous use of the HVAC system resulted in large amounts of moisture entering the building envelope. Serious moisture problems developed less than one year after the building was completed.

The enclosed ice rink also suffered from the lack of an adequate interior vapor retarder and HVAC system. The roof membrane acted as an exterior vapor retarder, keeping moisture within the roof decking and insulation. Additionally, there was no means for removing excessive interior moisture. Decay of the roof decking probably started soon after the ice rink was installed.

References

- [1] *1993 ASHRAE Handbook Fundamentals*, American Society of Heating, Refrigerating, and Air Conditioning Engineers, Inc., Atlanta, GA, 1993.
- [2] *Comparative Climatic Data for the United States through 1985*, United States Department of Commerce, National Climatic Data Center, Asheville, NC, 1986.
- [3] 1981 ASHRAE Handbook Fundamentals, American Society of Heating, Refrigerating, and Air Conditioning Engineers, Inc., Atlanta, GA, 1981.